



Replacement Sheet

BEST AVAILABLE COPY




Fig. 1

Replacement Sheet






Fig. 2






FIG. 4

# Replacement Sheet






Fig. 5




6A

SEM Micrograph of Group B at 300x after Electrochemical Test.




6B

SEM Micrograph of Group B at 700x after electrochemical test.




7A




7B

SEM micrographs of the Hayes CrCoMo sample after ASTM F746 corrosion test indicates intergranular corrosion attacks.




7C




7D

SEM micrographs of the Hayes CrCoMo sample after ASTM F746 corrosion test exhibiting corrosion attacks.

Replacement Sheet



8A



8B

SEM micrographs of the Hayes CrCo sample prior to any corrosion test.

**This Page is Inserted by IFW Indexing and Scanning  
Operations and is not part of the Official Record**

**BEST AVAILABLE IMAGES**

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images include but are not limited to the items checked:

- ☐ **BLACK BORDERS**
- ☐ **IMAGE CUT OFF AT TOP, BOTTOM OR SIDES**
- ☐ **FADED TEXT OR DRAWING**
- ☐ **BLURRED OR ILLEGIBLE TEXT OR DRAWING**
- ☐ **SKEWED/SLANTED IMAGES**
- ☐ **COLOR OR BLACK AND WHITE PHOTOGRAPHS**
- ☐ **GRAY SCALE DOCUMENTS**
- ☐ **LINES OR MARKS ON ORIGINAL DOCUMENT**
- ☐ **REFERENCE(S) OR EXHIBIT(S) SUBMITTED ARE POOR QUALITY**
- ☐ **OTHER:** \_\_\_\_\_

**IMAGES ARE BEST AVAILABLE COPY.**

**As rescanning these documents will not correct the image problems checked, please do not report these problems to the IFW Image Problem Mailbox.**